

OUT57949

SECRET 120313Z

1966 MAR 12 03 24Z

6655

25X1

1. CAMERA B 7 WAS USED IN MISSION 8076 FLOWN ON 10 MARCH 1966. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS FROM FAIR TO GOOD. THE FAIR RATING IS BECAUSE OF SMEAR CAUSED BY VEHICLE MANEUVERS.

B. 9R SIDE: MINOR ROLLER CHATTER IS PRESENT ALONG BOTH EDGES THROUGHOUT THE MISSION. MINOR EDGE STATIC OCCURS INTERMITTENTLY 14 MAR 1966 ALONG THE OUTBOARD EDGE. FOGGED STREAKS, ENTER THE FORMAT FROM THE OUTBOARD EDGE, RUN DIAGONALLY FOR 2.0" TOWARD THE TAKE-UP ENDS OF FRAMES 1450, 1666, 1728, 1738 AND 1893. A HEAT SPLICE IS PRESENT THROUGH FRAME 1275 AND A MANUFACTURING SPLICE THROUGH FRAME 1154.

C. 9L SIDE: EDGE STATIC IS PRESENT ALONG BOTH EDGES OF THE FILM THROUGHOUT THE MISSION. ROLLER CHATTER IS INTERMITTENTLY PRESENT ALONG THE INBOARD EDGE. THERE ARE TWO ROWS OF MINUS DENSITY DOTS ALONG THE INBOARD EDGE OF THE FILM. THEY ARE BOTH 1.5" APART BUT 0.8" AND 1.7" FROM THE INBOARD EDGE. THE ROW 0.8" FROM THE EDGE IS ONLY VISIBLE FOR APPROXIMATELY THE FIRST 200 FRAMES. THE ROW THAT IS 1.7" FROM THE EDGE IS INTERMITTENTLY DETECTABLE THROUGHOUT THE MISSION. THERE IS A SPLASH-TYPE LIGHT LEAK ALONG THE OUTBOARD EDGE OF FRAMES 655, 729 AND 886. HEAT SPLICES ARE PRESENT IN FRAME 1289 AND BETWEEN FRAMES 1602/1603 AND 1625/1626. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1468.

DISTRIBUTION		
Cy No.	Office	Action
1	100	
	101	
	102	
	103	
	104	
	105	
	106	
	107	
	108	
	109	
	110	
	111	
	112	
	113	
	114	
	115	
	116	
	117	
	118	
	119	
	120	
	121	
	122	
	123	
	124	
	125	
	126	
	127	
	128	
	129	
	130	
	131	
	132	
	133	
	134	
	135	
	136	
	137	
	138	
	139	
	140	
	141	
	142	
	143	
	144	
	145	
	146	
	147	
	148	
	149	
	150	
	151	
	152	
	153	
	154	
	155	
	156	
	157	
	158	
	159	
	160	
	161	
	162	
	163	
	164	
	165	
	166	
	167	
	168	
	169	
	170	
	171	
	172	
	173	
	174	
	175	
	176	
	177	
	178	
	179	
	180	
	181	
	182	
	183	
	184	
	185	
	186	
	187	
	188	
	189	
	190	
	191	
	192	
	193	
	194	
	195	
	196	
	197	
	198	
	199	
	200	
	201	
	202	
	203	
	204	
	205	
	206	
	207	
	208	
	209	
	210	
	211	
	212	
	213	
	214	
	215	
	216	
	217	
	218	
	219	
	220	
	221	
	222	
	223	
	224	
	225	
	226	
	227	
	228	
	229	
	230	
	231	
	232	
	233	
	234	
	235	
	236	
	237	
	238	
	239	
	240	
	241	
	242	
	243	
	244	
	245	
	246	
	247	
	248	
	249	
	250	

Advance copy  
Serialized

SECRET

-2-

D. STARTING AT FRAME 308 THE CAMERA REMAINED IN THE 1L POSITION AND CONTINUED THIS WAY THROUGHOUT THE MISSION. THE LAST TITLED FRAME IS 2596.

E. A CAMERA MALFUNCTION RESULTED IN ONLY THE 1L POSITION BEING RECORDED IN FRAMES 308 THRU 2596. THERE WERE NO PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS FAIR TO GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 15 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--

1